

EQUIPMENT ALERT

10EA-02-001

Date: January 12, 2010

Models: Genie GTH-1048 & GTH-1056

Serial Numbers: GTH1007B – 7101 To 7251, GTH1007A – 11697 To 11770, GTH1008A – 11785 To 13539, GTH1009A – 13543 To 13704, GTH1010A – 13713 To 13748

Subject: Parking Brake Release Unintentionally

Action should be taken on this Alert according to the table below.

	Machine should be shut down and taken out of service immediately upon receipt of alert. Machine cannot be placed back into service until all instructions contained in this alert are complied with and machine is approved for work by BEO.
X	Machine should be inspected in accordance with the attached Equipment Alert within ____ operational hours.
	This alert is for informational purposes only. No further action is required on your part.

Issue: It has come to our attention that Manlifts models GTH-1048 and GTH-1056 under certain conditions the parking brake may release unintentionally. If this occurs, the machine could roll out of control which may result in a collision or create another hazard.

Action: **READ THE ENTIRE PROCEDURE BEFORE STARTING WORK!!!**

- 1. Locate all machines and order parts by completing form.**
- 2. Perform adding latching relay to the parking brake within 30 days from receipt of parts.**
- 3. Notify BEO when all work is complete.**

**If you have any questions regarding this Equipment Alert Please Contact:
BEO Service Department**

7021 Easthaven Blvd. Houston, Texas 77017· 281-202-8168

jtoccton@bechtel.com · kgburke@bechtel.com · rggrande@bechtel.com



Campaign Bulletin 090016

Date: January 12, 2010
Subject: Parking Brake
Models Affected: GTH-1048 & GTH-1056
Serial Numbers Affected: GTH1007B – 7101 to 7251
GTH1007A – 11697 to 11770
GTH1008A – 11785 to 13539
GTH1009A – 13543 to 13704
GTH1010A – 13713 to 13748
Allowable Hours: 30 minutes

Issue:

Genie Industries has determined that, under certain conditions on the above referenced machines, the parking brake may release unintentionally. **If this happens, the machine could roll out of control which may result in a collision or create another hazard.**

Action:

This bulletin requires adding a latching relay to the parking brake switch circuit. This will ensure that if the parking brake switch is in the off position when the ignition key is turned on, the parking brake will remain set.

1. Locate all machines within the serial number ranges shown above.
Note: Enclosed is a list of affected machines under your account. You may have more machines within the serial range shown above and/or you may have sold or destroyed some units. Use the enclosed Owner Update Form to indicate the new location or status of any of your machines.
2. Until the kit is installed, make sure that the parking brake is in the "on" position before turning the ignition key in the "on" position per the operator's manual.
3. Fill out the attached parts order form to receive, at no charge, a Parking Brake kit with installation instructions.

Installation must take place as soon as possible, but no later than 30 days from receipt of parts.

**FAILURE TO COMPLETE THIS BULLETIN MAY
RESULT IN DEATH OR SERIOUS INJURY.**

Genie industries, Inc., 18340 NE 76th Street Redmond WA 98052, Ph: 800-536-1800, 425-881-1800



Campaign Bulletin 090016

4. Fill out and sign the completion form included with the instructions in the parts kit and fax to Genie's warranty department to verify that this campaign bulletin has been completed.

Warranty:

The labor and travel miles required to perform this inspection and installation are covered under the provisions of our warranty agreement. Labor for each affected machine will be paid at a rate of \$60.00 U.S. per hour and travel at a rate of \$.50 U.S. per mile, converted into the currency of the appropriate country at the time of payment.

If you are the owner of an affected machine and are not an authorized Genie dealer, please contact your nearest Genie dealer for assistance with this campaign bulletin. Only Genie Authorized Dealers will be reimbursed for labor or any other costs associated with this bulletin under the provisions of our standard warranty terms and conditions.

Genie and ANSI requires that the seller of a Genie machine report to Genie the model and serial number of each machine sold, as well as the name, address, and telephone number of the new owner, within 60 days of the sale. OSHA and ANSI also require that the manufacturer's campaign bulletins be completed. It is your responsibility to communicate this important information to all machine owners and applicable branches. If you require additional copies of this bulletin or have any questions, please contact Genie's service department at:

Unites States	800-536-1800
Canada	425-881-1800
All other locations	001-425-881-1800

Enclosures:

- Owner update form
- Parts order form
- Machine list report

**FAILURE TO COMPLETE THIS BULLETIN MAY
RESULT IN DEATH OR SERIOUS INJURY.**

Genie industries, Inc., 18340 NE 76th Street Redmond WA 98052, Ph: 800-536-1800, 425-881-1800



Campaign Bulletin 090016

Owner Update Form
(for updating machine owner information only)

Genie and ANSI requires that the seller of a Genie machine report to Genie the model and serial number of each machine sold, as well as the name, address, and telephone number of the new owner, within 60 days of the sale.

- If you have sold a machine, list the complete model and serial number (example: GTH1007B-7251 or GTH1008A-13539) and the name, address and phone number of the new owner

New Owner Information:

	Machine 1	Machine 2	Machine 3
Model*	<input type="text"/>	<input type="text"/>	<input type="text"/>
Serial Number*	<input type="text"/>	<input type="text"/>	<input type="text"/>
Owner Name*	<input type="text"/>	<input type="text"/>	<input type="text"/>
Address 1*	<input type="text"/>	<input type="text"/>	<input type="text"/>
Address 2	<input type="text"/>	<input type="text"/>	<input type="text"/>
City/State/Zip*	<input type="text"/>	<input type="text"/>	<input type="text"/>
Phone Number*	<input type="text"/>	<input type="text"/>	<input type="text"/>
Contact Person	<input type="text"/>	<input type="text"/>	<input type="text"/>

* Required fields.

Seller Information:

Date: _____

Company Name: _____

Account #: _____

Address: _____

(street) _____

(city) _____

State, zip code _____

Phone #: _____

- List any machines that could not be inspected or repaired because of the following:

Model & Serial Number	Scrapped	Exported	Stolen	Others (explain)
_____	-	-	-	_____
_____	-	-	-	_____
_____	-	-	-	_____
_____	-	-	-	_____

Fax to:

United States	877-738-7530
Canada	425-498-7530
All other locations	001-425-498-7530



Campaign Bulletin 090016

Parts Order Form

Fax this form to Genie Industries to receive the indicated Relay Kit Parking Brake for your machine. List the model and serial number of each affected machine.

Kit Part Number: 141899 – Relay Kit, Parking Brake

Please list the complete model and serial number (example: GTH1007B-7251 or GTH1008A-13539)

Model and Serial Number

Model and Serial Number

Date: _____
Company Name: _____
Ordered by: _____
Account # (if applicable): _____
Address: _____
(street): _____
(city): _____
(state, zip code): _____
Phone: _____

Send Parts to: (If you would like to send parts to a different location)

Company Name: _____
Attn: _____
Account # (if applicable): _____
Address: _____
(street): _____
(city): _____
(state, zip code): _____
Phone: _____

Fax to: United States 888-274-6192
Canada 425-556-8659
All other locations 001-425-556-8659